

Vehicle Detail Report

Volkswagen T-Cross 2022 280TSI DSG Two-wheel drive comfortable PLUS

Basic Information

Brand	Volkswagen
Mileage	35,000 km
Color	White
First Registration	2023-03-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Inner side of left C-pillar, Scratch. 2. Front bumper, Paint chip, Scrape. 3. Rear bumper, Paint chip, Scrape. 4. Windshield, Stone chip. 5. Left tail light, Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.