

Vehicle Detail Report

Volkswagen Lamando 2022 Lamando L 280TSI DSG Spicy Edition

Basic Information

Brand	Volkswagen
Mileage	33,000 km
Color	Dark gray
First Registration	2023-01-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Right rocker panel, Paint repair, Outer-side body panel repair. 2. Driver's seat rails and frame, Signs of removal.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.