

Vehicle Detail Report

Toyota Levin 2024 Dual Power 1.8L Leading Edition

Basic Information

Brand	Toyota
Mileage	14,000 km
Color	White
First Registration	2025-01-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Left rocker panel, Scratch damage. 2. Right rocker panel, Scratch damage. 3. Driver's seat rails and frame, Signs of removal. 4. Front passenger seat rails and frame, Signs of removal. 5. Driver's seat, Signs of removal, Modified. 6. Front passenger seat, Signs of removal, Modified. 7. Rear seats, Signs of removal, Modified.

"●"	= Standard equipment
"_"	= Not available
"○"	= Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.