Vehicle Detail Report

Geely Coolray 2025 1.5L CVT Superpower edition

Basic Information

Brand	**Geely**
Mileage	**4,000 km**
Color	**Dark gray**
First Registration	**2025-05-01**
Transfer Count	**0**

Vehicle Images























Vehicle Condition

1. Left front door: Paint chip. 2. Right front door: Paint chip. 3. Right rear door: Paint chip. 4. Right front fender: Paint chip. 5. Windshield: Impact damage.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.