

# Vehicle Detail Report

## Volkswagen Lavida 2024 1.5L Automatic escape version

### Basic Information

Brand	Volkswagen
Mileage	60,000 km
Color	White
First Registration	2024-01-01
Transfer Count	1

### Vehicle Images





## Vehicle Condition

1. Left rocker panel, Outer-side deformation. 2. Right rocker panel, Paint repair, Outer-side deformation. 3. Inner side of left C-pillar, Paint repair. 4. Inner side of right B-pillar, Dent. 5. Front bumper, Paint repair, Deformation, Scrape. 6. Rear bumper, Paint repair, Deformation, Scratch damage. 7. Left front door, Paint repair, Body panel repair. 8. Right front door, Paint repair, Body panel repair, Scratch damage. 9. Left rear door, Paint repair, Body panel repair. 10. Right rear door, Paint repair, Body panel repair, Scrape. 11. Left front fender, Paint repair, Body panel repair. 12. Right front fender, Paint repair, Body panel repair. 13. Left rear quarter panel, Paint repair, Body panel repair. 14. Right rear quarter panel, Deformation, Paint repair.

---

"●" = Standard equipment

"\_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.