

Vehicle Detail Report


Hyundai Tucson 2020 280TGD_i Dual-clutch two-drive smart joint version Country VI

Basic Information

Brand	Hyundai
Mileage	42,000 km
Color	White
First Registration	2020-11-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_ " = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.