Vehicle Detail Report

Toyota Wildlander 2022 2.0L Two-wheel drive Luxury PLUS edition

Basic Information

Brand	**Toyota**
Mileage	**80,000 km**
Color	**Black**
First Registration	**2022-09-01**
Transfer Count	**0**

Vehicle Images



























Vehicle Condition

1. Right bottom edge beam: Right rocker panel, Scratch damage. 2. Right C-pillar edge: Inner side of right C-pillar, Scratch. 3. Left rear quarter panel: Scratch. 4. Right rear quarter panel: Scratch.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.