Vehicle Detail Report

Hyundai ix25 2015 2.0L Automatic four-wheel drive premium model DLX

Basic Information

Brand	**Hyundai**
Mileage	**110,000 km**
Color	**Orange**
First Registration	**2014-12-01**
Transfer Count	**0**

Vehicle Images









Vehicle Condition

1. Left, B, Column Sealing, Inner side of left B-pillar, Dent, Non-accident-related deformation. 2. Right, B, Column Sealing, Inner side of right B-pillar, Dent, Non-accident-related deformation. 3. Rear body panel, Deformation. 4. Left rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.