

Vehicle Detail Report


Kia Run 2015 1.6L Automatic two-wheel drive GLS

Basic Information

Brand	Kia
Mileage	106,000 km
Color	White
First Registration	2016-03-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left roof side member, Left upper side rail, Paint repair, Body panel repair.
 2. Right, B, Column Sealing, Inner side of right B-pillar, Non-accident-related deformation. 3. Driver's seat slide rail, Driver's seat rails and frame, Corrosion. 4. Left rear quarter panel, Paint repair. 5. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.