


Vehicle Detail Report


Honda CR-V 2024 240TURBO CVT Two-wheel drive Shang 5 Seat plate

Basic Information

Brand	Honda
Mileage	39,000 km
Color	Black
First Registration	2024-03-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Inner side of left C-pillar, Scratch. 2. Inner side of right C-pillar, Scratch. 3. Driver's seat rails and frame, Signs of removal. 4. Front passenger seat rails and frame, Signs of removal. 5. Left rear quarter panel, Deformation. 6. Right rear quarter panel, Deformation.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.