

# Vehicle Detail Report

Hyundai Tucson 2021 Tucson L 1.5T GLX Two-wheel drive elite version

## Basic Information

Brand	Hyundai
Mileage	91,000 km
Color	Dark gray
First Registration	2021-10-01
Transfer Count	0

## Vehicle Images





## Vehicle Condition

1. Right upper side rail, Deformation. 2. Inner side of left A-pillar, Corrosion. 3. Inner side of left B-pillar, Scratch, Non-accident-related deformation. 4. Inner side of right B-pillar, Dent. 5. Driver's seat rails and frame, Signs of removal. 6. Front passenger seat rails and frame, Signs of removal. 7. Headliner, Soiling. 8. Headliner, Soiling.

---

"●" = Standard equipment

"\_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.