

Vehicle Detail Report

Hyundai ix25 2015 1.6L Automatic two-wheel drive noble type DLX

Basic Information

Brand	Hyundai
Mileage	65,000 km
Color	White
First Registration	2016-12-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Right upper side rail, Paint repair. 2. Left rear quarter panel, Paint repair, Body panel repair. 3. Right rear quarter panel, Paint repair, Body panel repair.

- "●" = Standard equipment
- "-" = Not available
- "○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.