

# Vehicle Detail Report

BMW X6 M 2021 X6 M

## Basic Information

Brand	BMW
Mileage	20,000 km
Color	Black
First Registration	2023-05-01
Transfer Count	0

## Vehicle Images





## Vehicle Condition

1. Front bumper, Deformation, Scratch damage. 2. Rear bumper, Scratch damage. 3. Right front door, Scratch. 4. Trunk lid, Scratch. 5. Left tail light, Scratch. 6. Right tail light, Scratch.

"●" = Standard equipment

"\_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.