

Vehicle Detail Report



Jetour X70 PRO 2023 1.5T DCT Comfortable 7 seat

Basic Information

Brand	Jetour
Mileage	19,000 km
Color	Black
First Registration	2023-07-01
Transfer Count	1

Vehicle Images







Vehicle Condition

1. Left upper side rail, Deformation. 2. Right upper side rail, Deformation. 3. Hood, Deformation, Scratch. 4. Front bumper, Paint chip, Scratch damage. 5. Left front door, Paint chip. 6. Right front door, Paint chip, Body panel repair, Deformation. 7. Left rear door, Deformation. 8. Right rear door, Paint chip, Deformation. 9. Left front fender, Deformation.

"●" = Standard equipment

"_ " = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.