



Vehicle Detail Report

BYD Song Pro 2024 DM-i Glory Edition 71km Pilot type

Basic Information

Brand	BYD
Mileage	21,000 km
Color	White
First Registration	2024-05-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left rocker panel, Scratch damage. 2. Driver's seat rails and frame, Signs of removal. 3. Hood, Scratch. 4. Front bumper, Paint repair, Scratch damage. 5. Rear bumper, Scratch damage. 6. Left front door, Scratch damage, Deformation. 7. Right front door, Deformation, Scratch. 8. Left rear door, Deformation, Scratch. 9. Right rear door, Deformation, Scratch damage. 10. Trunk lid, Deformation. 11. Left front fender, Deformation, Paint repair, Scratch. 12. Windshield, Scratch, Stone chip. 13. Driver's seat, Damage. 14. Body floor pan, Aftermarket underbody coating.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.