

Vehicle Detail Report

Volkswagen Teramont 2025 Teramont Pro 450TSI Four-wheel drive vertical and horizontal version

Basic Information

Brand	Volkswagen
Mileage	1,500 km
Color	Blue
First Registration	2026-03-01
Transfer Count	0

Vehicle Images







Vehicle Condition

1. Hood, Scratch. 2. Front bumper, Scratch damage. 3. Rear bumper, Scratch damage. 4. Right rear door, Paint chip, Scratch. 5. Left tail light, Scratch. 6. Right tail light, Water stain.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.