

Vehicle Detail Report


Hyundai ix35 2021 240T GDi DCT Two-wheel drive leading version GLS

Basic Information

Brand	Hyundai
Mileage	46,000 km
Color	Dark gray
First Registration	2021-07-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Inner side of left B-pillar, Deformation, Non-accident-related deformation.
2. Inner side of left C-pillar, Scratch.
3. Inner side of right B-pillar, Deformation, Non-accident-related deformation.
4. Driver's seat rails and frame, Signs of removal.
5. Front passenger seat rails and frame, Signs of removal.
6. Left rear quarter panel, Scratch, Deformation.
7. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.