


Vehicle Detail Report


Toyota Corolla 2018 Dual Power 1.8L E-CVT
Zhishang Edition China V

Basic Information

Brand	Toyota
Mileage	79,000 km
Color	White
First Registration	2018-09-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Radiator support, Signs of removal. 2. Left bottom side member, Left rocker panel, Paint repair. 3. Left, B, Column Sealing, Inner side of left B-pillar, Scratch. 4. Rear body panel, Deformation. 5. Driver's seat slide rail, Driver's seat rails and frame, Signs of removal. 6. Left rear quarter panel, Paint repair, Body panel repair. 7. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.