


Vehicle Detail Report


Geely Preface 2020 2.0T Flagship

Basic Information

Brand	Geely
Mileage	69,000 km
Color	Black
First Registration	2021-04-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Right roof side member, Right upper side rail, Paint repair. 2. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.