

Vehicle Detail Report

Toyota Sienna 2024 Dual Power 2.5L Platinum Edition

Basic Information

Brand	Toyota
Mileage	74,000 km
Color	White
First Registration	2024-07-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Right, A, Column Sealing, Inner side of right A-pillar, Deformation. 2. Right front fender lining, Right front fender structure, Deformation. 3. Rear seat frame and foam, Signs of removal. 4. Driver's seat slide rail, Driver's seat rails and frame, Signs of removal. 5. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 6. Headliner, Modified. 7. Left rear quarter panel, Paint repair, Body panel repair. 8. Right rear quarter panel, Paint repair, Body panel repair. 9. Headliner, Modified.

"●" = Standard equipment

"□" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.