Vehicle Detail Report

Toyota Corolla 2024 1.2T S-CVT Pioneer edition

Basic Information

Brand	**Toyota**
Mileage	**48,000 km**
Color	**White**
First Registration	**2024-08-01**
Transfer Count	**0**

Vehicle Images



















Vehicle Condition

1. Right C-pillar edge: Inner side of right C-pillar, Deformation (Not accident-related). 2. Right rear quarter panel: Paint repair, Body panel repair.

"●" = Standard equipment

"-" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.