

Vehicle Detail Report

Jetour X70S 2019 1.5T Auto Journey Edition 5 seat China V

Basic Information

Brand	Jetour
Mileage	100,000 km
Color	White
First Registration	2019-07-01
Transfer Count	0

Vehicle Images





Vehicle Condition

1. Left bottom side member, Left rocker panel, Outer-side deformation. 2. Right bottom edge beam, Right rocker panel, Outer-side deformation. 3. Left, B, Column Sealing, Inner side of left B-pillar, Scratch. 4. Right, C, Column Sealing, Inner side of right C-pillar, Scratch. 5. Trunk floor, Spare wheel well, Dust and sand residue. 6. Left front seat belt, Signs of removal, Replaced. 7. Headliner, Soiling. 8. Left rear quarter panel, Paint repair, Deformation. 9. Driver's seat, Driver's seat, Wear. 10. Headliner, Soiling. 11. Left front seat belt, Signs of removal, Replaced.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.