


Vehicle Detail Report

Toyota Levin 2019 Dual Power 1.8H Sports
version Country VI

Basic Information

Brand	Toyota
Mileage	76,000 km
Color	White
First Registration	2020-05-01
Transfer Count	1

Vehicle Images





Vehicle Condition

1. Left roof side member, Left upper side rail, Paint repair. 2. Right roof side member, Right upper side rail, Paint repair. 3. Right front frame rail, Deformation. 4. Right, B, Column Sealing, Inner side of right B-pillar, Non-accident-related deformation. 5. Driver's seat slide rail, Driver's seat rails and frame, Signs of removal. 6. Passenger seat track, Front passenger seat rails and frame, Signs of removal. 7. Left rear quarter panel, Paint repair, Body panel repair. 8. Right rear quarter panel, Paint repair, Body panel repair.

"●" = Standard equipment

"_" = Not available

"○" = Optional equipment.

Note: These are Chinese market vehicles. Warranty coverage is not available outside of China.